

# PROPERTY SUMMARY REPORT

PREPARED BY

Client
Apr 2, 2025



Where Drones Meet Due Diligence

Delivering aerial insight and thermal precision to support smarter property decisions — thank you for choosing us as your inspection partner.

## 3600 Hacienda Blvd, Davie, FL



Property Address: 3600 Hacienda Blvd, Davie, FL 33314

**Date of Inspection**: 04/02/2025 **Roof Type**: Fibertite Single Ply **Roof Installation Year**: 2011

**Age of Roof**: 14 years

**Roof Layer**: Existing Overlay

Warranty Status: Expires 10/26/2026

Scope of Work:

• Aerial roof inspection using high-resolution RGB imagery


• Supplemental thermal imagery captured (overview only)

• Oblique and overhead perspectives to show condition and structure


• No mapping or measurement needed

### **Photos**





























#### **Observations**

#### **Observations (Visual)**:

No immediate structural concerns visible from the exterior. No patch work and/or roof debris observed. Roof in good condition.

#### **Observations (Thermal)**:

Little to no thermal anomalies detected. Moderate cool spots were observed near areas with visible dirt buildup roof surface. Consistent shading in thermal variances indicate a healthy roof structure.

Captured By: Wilmar Saint Preux, ITC Certified Aerial Thermographer, FAA Certified Drone Pilot

**Company**: UAV Miami LLC **Inspection Date**: April 2<sup>nd</sup>, 2025

Disclaimer: The information, images, and thermal data provided in this report are for informational and educational purposes only. While care has been taken to capture and present accurate visual and thermal observations, we do not make any claims or representations as licensed roofing contractors, engineers, or building inspectors. This report is not intended to serve as a substitute for a professional roofing assessment, structural evaluation, or moisture analysis by a qualified and licensed professional. Clients are strongly encouraged to consult with appropriate industry experts before making any repair, maintenance, or purchase decisions based on the information presented herein. Do not rely solely on this report for decision-making related to property condition or value.